Trail Condition Monitoring

Trail Number: **507** **Cottonwood**

Non-Compliant Portions

TRLSEGID	Map ID	Issue	Field Msmt	Std Min	Std Max	Length(ft)	Description	Prescription
507.01	103	Clearing width	8 ft	12		50	Clearing width 8' due to overgrown tree.	Tree trimmers/pruners needed to cut back vegetation.
507.01	104	Tread width	4 ft	8	10	102	Tread width is 4' due to overgrown vegetation.	Grub out vegetation to widen tread on east side of trail.
507.01	107	Clearing height	5 ft	10		16	Clearing height is 5' due to overhanging branches.	Extended tree trimmer needed to cut low-lying branches.
507.01	108	Clearing height	5 ft	10		153	Clearing height is 5' due to overhanging branches.	Extended tree trimmer needed to cut low-lying branches.
507.01	109	Clearing height	5 ft	10		61	Clearing height is 5' due to overhanging branches.	Extended tree trimmer needed to cut low-lying branches.
507.01	113	Clearing height	5 ft	10		33	Clearing height is 5' due to overhanging branches.	Extended tree trimmer needed to cut low-lying branches.
507.01	117	Clearing height	7 ft	10		28	Clearing height is 7' due to low-lying branches.	Extended tree trimmer needed to cut low-lying branches.
507.01	119	Clearing height	5 ft	10		33	Clearing height is 5' due to low-lying branches.	Extended tree trimmer needed to cut low-lying branches.
507.01	121	Clearing width	8 ft	12		45	Clearing height is 8' due to low-lying branches.	Tree trimmers/pruners needed to cut back vegetation.
507.01	122	Clearing height	5 ft	10		58	Clearing height is 5' due to low-lying branches.	Extended tree trimmer needed to cut low-lying branches.

Maintenance Issues

TRLSEGID	MapID	Issue	Width(ft)	Length(ft)	Description	Prescription
507.01	101	Drainage	10	44	Drainage problem (puddle of water) 10' wide. Might cause widening of trail.	Fill low lying area with rock, gravel, roadbase and soil.
507.01	102	Drainage	12	66	Drainage problem (puddle of water) 12' wide. Causing widening of trail.	Fill low lying area with rock, gravel, roadbase and soil.
507.01	105	Drainage	7	17	Drainage problem 7' wide. Might cause widening of trail.	Fill low lying area with rock, gravel, roadbase and soil. Construct drainage on north side of trail.

507.01	106	Drainage	7	30	Drainage problem 7' wide. Might cause widening of trail.	Fill low lying area with rock, gravel, roadbase and soil. Construct drainage on south side of trail.
507.01	114	Drainage	10	18	Drainage problem (puddle of water) 10' in width. Causing braiding of trail.	Fill low lying area with rock, gravel, roadbase and soil. Construct drainage on east side of trail.
507.01	115	Drainage	10	23	Drainage problem (puddle of water) 10' in width. Causing braiding of trail.	Fill low lying area with rock, gravel, roadbase and soil. Construct drainage on east side of trail.
507.01	116	Drainage	10	17	Drainage problem (puddle of water) 10' in width. Causing widening of trail.	Fill low lying area with rock, gravel, roadbase and soil. Construct drainage on east side of trail.
507.01	118	Drainage	10	49	Drainage problem 10' in width. Causing widening of trail.	Fill low lying area with rock, gravel, roadbase and soil.
507.01	120	Drainage	10	26	Drainage problem (puddle of water) 10' in width. Causing widening of trail.	Fill low lying area with rock, gravel, roadbase and soil.
507.02	201	Drainage	15	111	Drainage problem 15' in width. Causing widening of trail.	Fill low lying area with rock, gravel, roadbase and soil. Reveg trail braids.
507.02	202	Braiding	10	94	Trail braiding occurring.	Reveg trail braid.

Constructed Features

TRLSEGID	Map ID	Feature Type	Length	Width	Height	Description
507.01	110	steel culvert	22	2	2	Functioning w/in standard
507.01	111	steel culvert	20	3	3	Functioning w/in standard