Trail Condition Monitoring

Trail Number: **508** **Sawhill Ponds**

Non-Compliant Portions

TRLSEGID	Map ID	Issue	Field Msmt	Std Min	Std Max	Length(ft)	Description	Prescription
508.03	301	Clearing width	3 ft	6		25	Clearing width is 3' due to fallen tree narrowing trail corridor.	Fallen tree needs to be removed.

Maintenance Issues

TRLSEGID	MapID	Issue	Width(ft)	Length(ft)	Description	Prescription
508.02	201	Drainage	8	41	Drainage problem (puddle of water) 8' in width.	Fill low lying area with rock, gravel, and soil. Construct drainage on north side of trail.
508.02	202	Erosion	5	18	Erosion problem 5' wide due to sloughing of trail down steep slope.	Construct a retaining wall on south side of trail to mitigate sloughing.
508.02	203	Drainage	10	30	Drainage problem (puddle of water) 10' in width. Causing widening of trail.	Fill low lying area with rock, gravel, and soil. Construct drainage on south side of trail.
508.02	204	Erosion	0	39	Erosion problem due to sloughing of trail down steep slope.	Construct a retaining wall on south side of trail to mitigate sloughing.
508.02	205	Erosion	10	21	Erosion problem 10' wide. Drainage problem due to low lying area. Widening of trail.	Fill low lying area with rock, gravel, and soil.

Constructed Features

TRLSEGID	Map ID	Feature Type	Length	Width	Height	Description
508.01	101	post/plank wall	15	1	3	Functioning w/in standard