Trail Condition Monitoring

Trail Number: **504** **East Boulder - Teller Lake Ac**

Non-Compliant Portions

TRLSEGID	Map ID	Issue	Field Msmt	Std Min	Std Max	Length(ft)	Description	Prescription
504.01	101	Tread width	2 ft	3		42	Tread width is 2' due to encroaching vegetation.	Weedwack and grub out vegetation to widen tread to at least 3'.
504.01	102	Tread width	1 ft	3		448	Tread width is 1' for almost whole length of trail. Trail is not usable for Accessibility.	Weedwack and grub out vegetation to widen tread to at least 3'.
504.01	103	Surface material	1			370	Surface material is vegetation. Trail is overgrown and needs serious attention to comply with Accessible standards.	Need to develop tread by weedwacking and grubbing out vegetation and filling with crusher fines material.
504.01	104	Clearing width	3 ft	8		11	Clearing width is 3' right at the entrance to the fishing pier.	Pruners needed to cut back encroaching vegetation.

Maintenance Issues

Constructed Features

TRLSEGID	Map ID	Feature Type	Length	Width	Height	Description
504.01	105	Other	50	8	0	Functioning w/in standard