Trail Condition Monitoring

Trail Number: **515** **East Boulder - Teller Lake #5**

Non-Compliant Portions

TRLSEGID	Map ID	Issue	Field Msmt	Std Min	Std Max	Length(ft)	Description	Prescription
515.01	103	Clearing height	5 ft	8		70	Low hanging branches from tree reducing clearing height to 5'.	Extended tree trimmer needed to cut low-lying branches.

Maintenance Issues

Constructed Features

TRLSEGID	Map ID	Feature Type	Length	Width	Height	Description
515.01	101	corrug. Plastic culvert	6	1	1	Functioning w/in standard
515.01	102	post/plank wall	16	1	2	Functioning w/in standard
515.01	104	post/plank wall	20	1	3	Functioning w/in standard