



### SUMMARY

- High seepage from unlined Dry Creek #2 Ditch
  - Recharge within Development area
  - Relatively high recharge below existing residential areas due to lawn/shrub irrigation
  - Large rise in ground water table within Keewaden Meadows Neighborhood
  - Basement sump-pumping in selected homes adjacent to ditch
- Project Area Before Development
1. Pasture irrigation and ditch leakage lead to localized ground water recharge
  2. Ground water recharge contributes to localized increases in the water table
  3. Storm water flows uninhibited from property

### LEGEND

- Property line
- ↔ Below Ground Ditch Seepage
- Irrigation Ditch
- Portion of Irrigation Ditch Currently Piped

# BOULDER CREEK COMMONS

Groundwater Summer Information  
Existing Conditions