# Betasso Capital Improvement Project November 2016 Update

**Progress To Date**

- Moltz Construction mobilized in early September

- Pipe gallery work

- Filter rehabilitation

- Dirt removal from the pre-treatment basins

- Clearwell inspection

- Dewatering building construction

**Upcoming Schedule**

- Betasso will be periodically offline in December for valve installation
- A tower crane will be installed in early December
- The double tee pretreatment building concrete roof will be removed and demoed
- Continued valve replacement
- Continued filter rehabilitation
- Clearwell roof replacement and interior paint preparation
- Continued dewatering building construction