BOULDER CITY-COUNTY HEALTH DEPARTMENT WATER SUPPLY INSPECTION REPORT

WATER QUALITY CONTROL SECTION

3450 BROADWAY BOULDER, COLORADO 80302

Population served 3 employees

Operating season year round

Facility Hendricks Mining Address 3000 N. 63rd St

Owner/Manager Thomas S. Hendricks 443-1502

Other facilities using this supply None

ITEM	COMMENTS
SOURCE Drilled well ✓ Dug Well ___ Depth 120 ft	- Well water used for toilets & sinks only.
Other	
Location In well pit on Valmont across from parking	
Well head above ground No Pitless adapter No	
Adequate cover ___ Casing condition	
Protection from flooding/contamination →	- Pit had some water at the bottom, but the sides were dry
Type of sewage disposal septic system	
Nature of and proximity to pollution sources	- Well is underground.
PUMP Type submersible	
Location in well	
STORAGE Pressure ✓ Gravity ___ Cistern ___	
Other reservoir None	
Total storage capacity ~ 82 Gal.	
Location in well pit	
Protection from contamination OK	
INITIAL TREATMENT Sedimentation ___ Coag./Floc. ___	
Filtration ___ Conditioning/softening ___	
Operating Properly	
DISINFECTION Provided ✓ Agent by chlorine city water	
Method by city water	
Operating Properly	
Adequate retention time	
Tap residual 0.0 mg/l Test kit	
SAMPLED Yes ✓ No ___ Results sampled well water safe	
PHYSICAL APPEARANCE	
OTHER POTABLE WATER PROVIDED? yes H&A Bottled H_2O	

You are hereby ordered to correct the following deficiencies within ___ days:

DATE 11/9/77 SANITARIAN Judy Watkins 441-3596

OPERATOR Thomas S. Hendricks

HENDRICKS MINING

P. O. BOX 653 — CARIBOU