BOULDER CITY-COUNTY HEALTH DEPARTMENT
WATER QUALITY CONTROL SECTION
3450 Broadway
Boulder, Colorado 80302

WATER SUPPLY INSPECTION FORM

Water Supply: Hendricks Mining Co. Address: 3000 N 63rd

Owners Name: Tom Hendricks, Ken Good Address: Same Phone: 443-1502

Population Served: 17 Taps: 1 Season: Yr Round

Glen - Fuerman

ITEM	COMMENTS
1. **SOURCE:** a. Drilled ____ Dug ____ Depth ____ Other: John Donnelly Ditch b. Location: S.W. of property c. Well Head ____ Pitless Adapter ____ d. Adequate Cover ____ Casing ____ e. Protection From Flooding/Runoff ____ f. Type and Distance to Pollution Sources ____	Bottled Water from Everclear out of Denver 1-14-81 1-21-81 Per phone conversation - check pump & storage next time in area. CR Also 80,000 gal storage tank on top of hill for fire protection on Grenell Mine.
2. **PUMP:** a. Type: 2 Cent. b. Location: By holding pond east of KOA on Valmont.	
3. **STORAGE:** a. Pressure ____ Gravity ✓ Other ____ b. Capacity: 10' x 10' deep c. Location: North of Mine d. Sanitary Condition: OK	
4. **TREATMENT:** a. Sedimentation ____ Coag./Floc. ____ Filters ____ Conditioning/Softening ____ Operation ____	
5. **DISINFECTION:** a. Provided ____ b. Agent ____ c. Method ____ d. Operation ____ e. Detention Time ____ f. Tap Residual ____ g. Test Kit ____	
6. **SAMPLE ANALYSIS:** a. Sample Taken: NO b. MF ____ c. Chemical ____	
7. **PHYSICAL TESTS:** ____	
8. **OTHER POTABLE WATER PROVIDED:** a. yes b. Source: Everclear	

DEFICIENCIES

You are hereby ordered to correct the following items within ____ days.

1-28-81
None Noted

Date: 1-21-81 Sanitarian: Chuck Gy Phone: 441-3596

Person Interviewed: Glenn E. Pfau