BOULDER CITY-COUNTY HEALTH DEPARTMENT
WATER QUALITY CONTROL SECTION
3450 Broadway
Boulder, Colorado 80302

WATER SUPPLY INSPECTION FORM

Water Supply: Hendricks Mining Co. Address: ~~3000 N 63rd~~ Valmont & 63rd

Owners Name: Tusco Inc Address: in care of 3000 N. 63rd Phone: 443-1502

Population Served: 10-12 Taps: 4 Season: Yr Round

ITEM

1. **SOURCE:** a. Drilled ____ Dug ____ Depth ____
   Other: Ditch & storage tank
   b. Location: West of Mine, N of Valmont
   c. Well Head: — Pitless Adapter: —
   d. Adequate Cover: — Casing: —
   e. Protection From Flooding/Runoff: NONE
   f. Type and Distance to Pollution Sources: ____

2. **PUMP:** a. Type: Centrif.
   b. Location: pump house by pond

3. **STORAGE:** a. Pressure ____ Gravity: ✓
   Other: ____
   b. Capacity: Unknown
   c. Location: Hill above Mine
   d. Sanitary Condition: OK

4. **TREATMENT:** a. Sedimentation ____
   Coag./Floc. ____ Filters ____
   Conditioning/Softening ____
   Operation ____

5. **DISINFECTION:** a. Provided: NO b. Agent ____
   c. Method ____
   d. Operation ____
   e. Detention Time ____
   f. Tap Residual ____ g. Test Kit ____

6. **SAMPLE ANALYSIS:** a. Sample Taken: NO
   b. MF ____ c. Chemical ____

7. **PHYSICAL TESTS:** ____

8. **OTHER POTABLE WATER PROVIDED:** a. yes
   b. Source: H & A Bottled Water from Denver

COMMENTS

all Bldgs equipped & served by H & A Bottled Water.

DEFICIENCIES

You are hereby ordered to correct the following items within ____ days.

None

Date: 1-26-82 Sanitarian: Chuck G[illegible] Phone: 441-3596

Person Interviewed: J Kissell

MW