BOULDER COUNTY HEALTH DEPARTMENT
Environmental Quality Section
3450 Broadway
Boulder, Colorado 80302 • 441-1185

WATER SYSTEM INSPECTION REPORT

Water System: Hendricks Milling Co. Address: 3000 N 63rd

Owner: Tasco Operator: SAA Phone: 443-1502

Population Served: ~5 Year-round: ✓ Seasonal: ____ Taps: 3-4

Community: ____ Non-community: ____ Class II: ____ Operating Season: Yr Round

ITEM

1. SOURCE: a. Drilled ____ Dug ____ Depth ____
   Other: Small collection pond
   b. Location: West of milling operation
   c. Well Head: — Pitless Adapter: —
   d. Adequate Cover: — Casing: —
   e. Protection From Flooding/Runoff: NONE
   f. Type and Distance to Pollution Sources: —

2. PUMP: a. Type: Centrif.
   b. Location: pump house by pond
   c. Number: 1 d. Capacity (GPM) ____

3. STORAGE: a. Pressure ____ Gravity ✓
   Other: large storage tank
   b. Capacity: Unknown
   c. Location: Hill North of mine
   d. Sanitary Condition: —

4. TREATMENT: a. Sedimentation ____
   Coag./Floc. ____ Filters ____
   Conditioning/Softening ____
   Operation ____

5. DISINFECTION: a. Provided: NO b. Agent ____
   c. Method ____
   d. Operation ____
   e. Detention Time ____
   f. Tap Residual ____ g. Test Kit ____

6. SAMPLE ANALYSIS: a. Sample Taken: NO
   b. MF ____ c. Chemical ____
   d. Nitrate ____

7. PHYSICAL TESTS: ____

8. OTHER POTABLE WATER PROVIDED: a. yes
   b. Source: Bottled - From Everclear (Denver

9. COMPLIANCE WITH SAMPLING
   Requirements ____

You are hereby ordered to correct the following items within ____ days.

Item # Violation(s)

Remarks ____

Inspection Time: 10 min
In: 3:20 Out: 3:30
Date: 2-5-85

Sanitarian: Chuck Gray Phone: 441-1196

Person Interviewed: J Novrah