Trail Condition Monitoring

Trail Number: **514** **Dry Creek**

Non-Compliant Portions

TRLSEGID	Map ID	Issue	Field Msmt	Std Min	Std Max	Length(ft)	Description	Prescription
514.02	202	Tread width	10 ft	1.5	6	105	Tread width is 12', there's a lack of tread definition.	Define the tread to 4-5 feet wide and reveg trampled areas. Bring washed out crusher fines material back up to the defined tread.
514.02	203	Tread width	14 ft	1.5	6	105	Tread width is 14', no tread definition. Visitors walk anywhere.	Define the tread to 4-5 feet wide and reveg trampled areas. Bring washed out crusher fines material back up to the defined tread.
514.02	207	Clearing width	4 ft	6		60	Overgrown bushes restricting clearing width.	Tree trimmers/pruners needed to cut back vegetation.
514.02	208	Tread outslope	13 %		5	24	Outslope is 13%.	Scrape uphill soil to downhill side of tread.
514.02	211	Clearing width	2 ft	6		116	Overgrown weeds along trail.	Weedwack weeds along sides of trail.
514.02	212	Clearing width	4 ft	6		40	Overgrown bushes encroaching on trail.	Tree trimmers/pruners needed to cut back vegetation.
514.02	213	Clearing width	4 ft	6		37	Overgrown bushes encroaching on trail.	Tree trimmers/pruners needed to cut back vegetation.

Maintenance Issues

TRLSEGID	MapID	Issue	Width(ft)	Length(ft)	Description	Prescription
514.02	204	Erosion	0	53	Geo-textile material is showing and deteriorating. Gravel is being eroded in places.	Collect loose geo-textile pieces and discard.
514.02	205	Erosion	3	186	Geo-textile material is showing and deteriorating. Gravel is being eroded in places.	Maybe re-install crusher fines raised treadway?

Constructed Features

TRLSEGID	Map ID	Feature Type	Length	Width	Height	Description
514.02	201	corrug. Plastic culvert	16	1	1	Functioning w/in standard