Trail Condition Monitoring

Trail Number: **513** **Cherryvale**

Non-Compliant Portions

Maintenance Issues

TRLSEGID	MapID	Issue	Width(ft)	Length(ft)	Description	Prescription
513.03	306	Drainage	8	26	Drainage problem 8' wide. Causing widening of trail.	Fill depression with gravel and soil. Construct drainage on south side of trail.

Constructed Features

TRLSEGID	Map ID	Feature Type	Length	Width	Height	Description
513.01	101	steel culvert	20	1	1	Disrepair
513.01	102	steel culvert	14	1	1	Disrepair
513.02	201	Steel w/ Headwall	40	1	1	Functioning w/in standard
513.02	202	drain dip	0	0	0	New feature needed
513.03	301	steel culvert	24	1	1	Functioning w/in standard
513.03	302	Steel w/ Headwall	26	1	1	Disrepair
513.03	303	Bottonless Arch Culvert	32	12	4	Functioning w/in standard
513.03	304	Bottonless Arch Culvert	16	2	2	Functioning w/in standard
513.03	305	Bottonless Arch Culvert	16	2	2	Functioning w/in standard