Trail Condition Monitoring

Trail Number: **503** **East Boulder - Teller Lake**

Non-Compliant Portions

TRLSEGID	Map ID	Issue	Field Msmt	Std Min	Std Max	Length(ft)	Description	Prescription
503.01	103	Clearing width	8 ft	28	12	52	Clearing width is 8'.	Tree trimmers/pruners needed to cut back vegetation.
503.02	207	Trail grade	10 %		12	46	Trail grade is 10%.	Possible re-alignment to attain grade of 8.33% for Accessibility spur to fishing pier.
503.04	401	Clearing width	2 ft	6		93	Encroaching vegetation is making clearing width 2'.	Need to grub out vegetation from tread.
503.04	403	Clearing width	3 ft	6		157	Encroaching vegetation is making clearing width 3'.	Need to grub out vegetation from tread or weedwack.

Maintenance Issues

Constructed Features

TRLSEGID	Map ID	Feature Type	Length	Width	Height	Description
503.01	102	steel culvert	22	1	1	Functioning w/in standard
503.01	104	steel culvert	20	1	1	Disrepair
503.01	105	Bottonless Arch Culvert	20	4	4	Functioning w/in standard
503.02	206	steel culvert	22	1	1	Functioning w/in standard
503.02	208	steel culvert	24	1	1	Functioning w/in standard