# Doudy Draw Trail Non-Compliance & Maintenance Issues

Segments 01, 02 & 03
were not surveyed.

01
03
04
05
07
08

2000 Imagery

Legend

Begin
End

Non-Compliance Indicator

Trail Grade

Maintenance Issue

None

Doudy Draw Trail

Segment 101.04

Other Trail

3

SH93 - S Foothills H...

Feet
0 125 250 375 500

E:\MapFiles\Trails\TrailConditionMonitoring\Maps\SouthTSA\DoudyDrawNGM.mxd

# Greenbelt Connector Trail Non-Compliance & Maintenance Issues

SH128

SH93 - S Foothills Hwy.

01

2000 Imagery

Legend

Begin

End

Non-Compliance Indicator

Tread Outslope

Maintenance Issue

None

Greenbelt Connector Trail

Segment 115.01

Segment 115.02

Other Trail

3

0 125 250 375 500 Feet

E:\MapFiles\Trails\TrailConditionMonitoring\Maps\SouthTSA\GreenbeltConnectorNCM1.mxd